

Employee Name:

SAFE WORKING PROCEDURE

Form: SWP

003

	POURING OF CONCRETE
1. THE TASK:	
Pouring of concrete.	
2. THE HAZARDS:	
	dard tools and equipment, Snakes and
-	or housekeeping, weather and Co-workers.
3. PERSONAL PROTECT	FIVE CLOTHING:
-	pots, Gloves, Eye protection, Dust mask and Reflecting vest in some cases
4. TOOLS:	
Spade, and wheel barrow.	
	IONS: (General Safety Precautions)
a. Be sober at all times.	
b. Do not smoke dagga or use drugs during working hours.	
c. Do not perform any task t	unless you have received specific training for the task.
	ped Personal Protective Equipment.
e. Do not wear loose clothin	ng when working near moving machinery.
6. Specific Safety Precauti	ons:
a. Beware of defective tools and equipment.	
b. Beware of hitting face, ha	ands, legs, and feet with tools and equipment.
c. All tools to be properly m	naintained.
d. Watch where you walk, is	s observant of co-workers.
e. Beware of sharp edges, T	Tripping hazards, excavations (holes) and hazardous materials.
f. Maintain a safe working of	distance between co-workers.
g. Use the correct PPE for the	•
h. Do not confront Snakes a	and wild animals (report to your supervisor and warn co-workers)
i. Do not horseplay on the j	job. (It can be dangerous)
J. do not spill cement on the	ground
k. Comply with all company and other signage.	
1. Comply with all company	•
<u> </u>	ituation or condition to your supervisor.
	instruction given to you by your supervisor.
	at in manner and area as per company policy.
p. To conserve the environment in all possible ways.(Housekeeping)	

Employee Signature: