

NGJ Hayter Pr Tech Eng
Structural Engineering Technologist

21 Greenwood Road
Boughton
Pietermaritzburg 3201

Tel: 082 339 2308
hayternoel@gmail.com
24 July 2023

Our ref: M23091
Your ref:
Please reply to: N Hayter

AMAFA
Monuments Council
Pietermaritzburg

Dear sirs


**ST ANTHONY'S CATHOLIC CHURCH
CORNER OF JABU NDLOVU AND RETIEF STREETS
PIETERMARTITZBURG
REPAIRS TO EXISTING ROOF STRUCTURES**

I hereby confirm that I was appointed as consulting structural engineer by the St Anthony Church Committee to oversee and assist in this matter.

The replacement of the entire timber structure including the steepie roof above the bell tower, was necessitated as the result of severe termite infestation of the timbers, photographs of which are appended to this letter.

I further confirm that the roof structure will be replaced with structural grade treated timber following the exact dimensions and profiles of the existing roof structure, and that the brickwork will not be altered in any way, so as to maintain the original appearance of the building. The new roof sheets will match the original corrugated profile. There will be no deviation from the existing brickwork structure, nor will there be any alterations or additions whatsoever.

In view of the above facts, I sincerely request that you reconsider the fine served on the Church as there have been no transgressions relating to any alterations or additions to the original building meets with your requirements. Should you have any queries regarding this report, kindly contact me.

Yours faithfully


NGJ Hayter

Pr Tech Eng 8870162

Proprietor: NGJ Hayter Pr Tech Eng ECSA MSAICE MIPET IMSAISC