

SALT & SUNSHINE MINISTRIES

37 Main Road, Malvern Tel: [+27-31] 464 1232

E-mail: info@saltandsunshine.co.za Website: <u>www.saltandsunshine.co.za</u>

19-02-2014

To whom it may Concern:

Address: 37 Main Road Malvern

Re: Amendments to Building

Roof:

- 1. The original corrugated sheeting has degenerated through time; water damage has also been one of the contributing factors for replacement.
- 2. We are a certified NGO and in terms of affordability, the IBR roof sheeting used on the alterations for the above mention site was most affordable.
- 3. We also took consensus of our neighboring sites and this was the common material used on most of the surrounding homes.

Floor:

- 1. The timber flooring was severely infected by wood borer.
- 2. Considering our purpose for building, the safety of our men, women and children was our primary focus.
- 3. The integrity of the original flooring was questionable in respect to safety.
- 4. The floors were therefore filled according to the specific construction standards.
- 5. Damp course standards were used to prevent moisture.

I thank you for your consideration.

Salt and Sunshine Ministries

Pastor Rajen Naidoo