

NATAL PEST SERVICES cc

Ck 1996/029598/23

- * Registered with the Department of Agriculture (Act 36 of 1947)
- * Approved Eradicators of all Wood-Destroying Insects.
- * Member of the South African Pest Control Association

58 HANNAH ROAD, CONGELLA 4001 P.O. BOX 17110, CONGELLA 4013 TEL: 031 205 5354 FAX: 031 205 0990 Email: info@natalpestservices.co.za



RESIDENTIAL

COCKROACH SERVICE
SILVERFISH
BED BUGS
FLEAS
ANTS
RODENT CONTROL
BIRD PROOFING
BIRD LICE
CARPET MOTH
ENTOMOLOGIST REPORTS
PROPERTY INSPECTIONS
TERMITE ERADICATION
BORER ERADICATION
LAWN TREATMENT



INDUSTRIAL

COCKROACH CONTROL
RODENT CONTROL
TERMITE PROOFING
PROPERTY INSPECTIONS
BIRD PROOFING
GRAIN INSPECTIONS
GRAIN FUMIGATIONS
WEED CONTROL
PHYTOSANITTARY CERT.



MARINE

SHIP FUMIGATIONS CONTAINER FUMIGATIONS COCKROACH SERVICE RODENT CONTROL 10th October 2013

M/s. D. Galetti c/o Collingwoods Property

Dear Sir/Madam

RE: 138 PARK ROAD, DURBAN NORTH

This letter of quotation is to be read in conjunction with the relevant Inspection Report No.D2252.

RECOMMENDATIONS

Woodborer

The main dwelling and garage are to be covered with plastic tarpaulins and fumigated with Methyl bromide gas (L2081) at a dosage rate of 48 grams per cubic metre of free air space. The exposure period will be for 18-24 hours.

The buildings must be vacated for a period of two days and two nights.

Security guards will be placed on the property for the duration of the fumigation only – once Natal Pest Services has left the premises, security thereafter is your responsibility. Unfortunately, due to the increase in the crime rate, we will be utilizing the services of a professional security guard.

GUTTERS, TILES, FACIA BOARDS, ETC

Whilst every precaution will be taken by our workmen not to damage them, we exonerate ourselves from any blame should they be damaged during the fumigation. All aerials/satellite dishes must be removed by the owner/occupier prior to fumigation.

N.B. The owners of the property must warn their immediate neighbours of the pending fumigation in order that they may take the necessary safety precautions regarding their pets and the occupiers of any building/s adjoining the fumigation.

White Ants

Page 2/

A BETTER SERVICE

Members: D.F. Ribbink, R.N. Ribbink, C. Ribbink



White Ants

The subfloor area and carport will be sprayed and the slab area pertaining to the garage as well as the cavity wall of the granny flat will be drilled and injected with a registered Termiticide (Termidor L6616) in accordance with The South African National Standards No.:10124.

PRICES:

The cost to fumigate the main dwelling and garage will be R10,600.00
The cost of the security guard will be R 200.00
The cost of the white ant treatments will be R 2,600.00
The Entomologist Report Fee is R 592.00
VAT inclusive.

The building is over 100 years old and the damage done by wood-destroying insects is severe. Should the purchaser opt to demolish the building, we require a letter in writing to this effect. The white ants however, should be carried out.

PUBLIC LIABILITY:

Our Public Liability and Workmens Compensation numbers are as follows:

WORKMENS COMPENSATION 0714-574-1000 PUBLIC LIABILITY NATAL025/0001

Our insurers are Hollard Insurance Company, the underwriters being Compendium Insurance Group (Pty) Ltd.

We trust that our quotations are acceptable to you, and should you wish further clarification kindly contract the writer who will willingly oblige.

Yours Faithfully
NATAL PEST SERVICES cc

SHAUN RUTHERFORD
Inspector

ACCEPTANCE (138 PARK ROAD)



NATAL PEST SERVICES cc

Ck1996/029598/23

58 HANNAH ROAD, CONGELLA 4001 P.O. BOX 17110, CONGELLA 4013

TEL: 031 205 5354 FAX: 031 205 0990 Email: info@natalpestservices.co.za

- Registered with the Department of Agriculture (Act36 of 1947)
- Approved Eradicators of all Wood Destroying Insects

Member of the South African Pest Control Association

Woodborer, Cryptotermes-brevis, Subterranean termites, Agricultural, Industrial and Domestic Pests

Houtboorders-Cryptptermes-brevis-Rysmiere Landboukundige, Industriele en Huishoudelike Plae

INSPECTION REPORT

Property Eiendom 138 Park Road

Durban North

Report No Verskag Nr D2252

Owner

M/s. D. Galetti

Inspected By

Shaun Rutherford (P21302)

Eienaar

Ondersoek

Purchaser

M/s. B. Jacklin

Agent

Collingwood Property

Koper

Estimated age of Property Geskattevan Eiendom

In excess of 100 years

Instruction From

William

Inspection Date

Ondersoek

10th October 2013

Type of Building and Roof

Tipe Gebou en Dak

Single Storey. Wood and Iron under Asbestos.

Suspended wooden floor.

Main Roof Hoof Dak

Accessible for inspection. Roof timbers are Oregon and Deal. Support timbers are exposed. Ceiling batons are exposed.

Evidence of Cryptotermes brevis (wood-destroying insect) activity and damage to roof timbers and ceiling boards - refer recommendations. N.B. MUST OBTAIN THE OPINION OF A REPUTABLE ROOFING

CONTRACTOR

Auxiary Roof Bykomende Dakke

Eaves / Dakrand

Extended and boxed.

Joinery Skrynwerk

S A Pine, Oregon and Meranti -- painted and varnished. Doorframes are wood. Window-frames are wood. Joinery has not been probed. Evidence of Cryptotermes brevis activity and damage as well as white ant

workings and damage to lounge external doorframe - refer recommendations.

Floors Vloere

Flooring comprises of novilon over suspended Oregon strip flooring boards (one can expect possible woodborer damage/activity once the floors are exposed) and exposed S A Pine tongue and groove flooring boards - suspended. Evidence of Cryptotermes brevis activity and damage to flooring boards - refer recommendations.

Subfloor area Ondervloer area Accessible for inspection. Support timbers are Oregon and Deal over brick/concrete foundation walls and dwarf pillars. Evidence of white ant workings and a nest - refer recommendations.

Outbuildings Buitegebou

Flat: Brick under Tile. Roof timbers are Oregon. Joinery is steel and wood. Concrete slab floor. Evidence of white ant workings and damage by ceiling boards - refer recommendations.

Carport/Single Garage: Brick under tile. Roof timbers are Oregon. Joinery is steel. Concrete slab floor. Steel garage door. Evidence of Cryptotermes brevis and white ant activity and damage - refer recommendations.

Fences/Heinings

Precast Concrete

SEE OVERLEAF FOR RECOMMENDATIONS AND CONDITIONS



D. GALETTI 138 PARK ROAD DURBAN NORTH TAX INVOICE

VAT REG. No. 4380/102/50/1

NATAL PEST SERVICES CC

*Registered with the Department of Agriculture (Act 36 of 1947).

* Approved Eradicators of all Wood-Destroying Insects.

*Member of the South African Pest Control Association.

58 HANNAH ROAD CONGELLA 4001 P.O. BOX 17110, CONGELLA 4013, TEL. 205 5354 FAX. 205 0990, Email: mwnps@mweb.co.za

Deliver to/Aanlewer aan M/S ZEILER JANKEY ATTORNEYS P.O. BOX 20488 DURBAM NORTH 116853 4016 Exemption reference Vrywaar verwysing Area Ruimte Account No. Your Reference Rekening Nr. U Verwysing Tax Belasting D2252 Page 1 Exclusive Date 10/10/13 Bladsy Datum

Code				ription rywing			Quantity Hoeveel	Ur Eenh		Unit Price Eenheidprys	Disc. % Kort %	Tax Belasting	Nett Netto Prys
Kode	337/06	THROR	OGIST F	ŒPORT MIGATI	ON & V	vhite . Endat	ANT IONS.					72.70 0.00 0.00	51 9 .30 0.00 0.00
			CC. NO NK - G			(MENT					Total nett		519.30
E	RANCE	I CODE	0: 04252 0: 0511	Ö							Discount Korting		0.00
·											Amount e Bedrag b		519.30
_		l	Fleas	Ticks	Lice	Rodents	White Ants	Ants	Silver Fish	Weevils	Tax Belasting		72.70
Insect Rodent	Cockroaches	Bedbugs			ļ		+		ľ	1 1	Delasiniç		20 I
Insect Rodent Chemical	Cockroaches Diazinon	Bedbugs	Deisekta	Lindane	Vapona DDVP	Warfarin (Finale)	Aldrin Protopam Chloride	Carbaryl	Diazinon	Mercapothion	<u> </u>	Total	592.00