

Archaeological Site Report	SiteNo	9/2/003/0082
	Site Name	9 Cross Street, Grahamstown
	Date	
	Project	
	CaseNID	
	Coords	-33.313506, 26.530477

Page No: 1 **SiteAutoID:** 88

Site Category: Building

SiteComments:

Archive Import History: ON 1863 MAP. THIS BUILDING C1830. Visual Description: SINGLE STOREY, DOUBLE PILE 3 BAY SYMMETRICAL PLAN AND ADDITION TO LEFT-HAND SIDE. FLAT CORRUGATED IRON ROOF. WALLS BRICK PLASTERED AND PARAPET. SMALL PANE SASH WINDOWS - PART OF GROUP. Colours: Site Features: Condition: Good Construction Date: Materials: Catalogue: Radford 1989 (b), No: T.15, Significance Category:

Damage Types: