Archaeological Site Report	SiteNo	9/2/003/0013
9	<b>Site Name</b>	56 Beaufort Street, Grahamstown
	Date	
	Project	
	CaseNID	
Page No: 1 SiteAutoID: 27	Coords	-33.313975, 26.527858

Site Category: Building

## **SiteComments:**

Archive Import History: Visual Description: DOUBLE STOREY, PART DOUBLE PILE 3 BAY SYMMETRICAL PLAN PLUS SINGLE STOREY ADDITIONS WITH PAGODA BOW WINDOWS. WOODEN DOUBLE STOREY VERANDAH. CORRUGATED IRON FLAT ROOFS. WALLS BRICK PLASTERED. ORIGINAL DOORS AND SMALL PANE SASH WINDOWS. Colours: Site Features: Condition: Good Construction Date: 1840c Materials: Catalogue: Radford 1989 (b), No: S.20, Significance Category:

## **AdminComments:**

ON 1863 MAP. ON C1867 PHOTO AS IS. SEE VAN DER RIET IX.14. LEWCOCK DATES C1840. SEE N.M.C. FILES. Bibliography archive:

Damage Types:

