

Archaeological Site Report	SiteNo	9/2/026/0005
	Site Name	City Hall, Oxford Street, East London
	Date	
	Project	
	CaseNID	
	Coords	-33.014680, 27.904254
Page No: 1 SiteAutoID: 28870		

Site Category: Building

Directions:

2/4

SiteComments:

Archive Import History: Visual Description: Double storied plastered brick. Corrugated iron pitched roof behind parapets. Doors and windows- wood. Special feature: Clock tower and copper clad Spire. Colours: Site Features: Condition: Good Construction Date: Completely restored 1990. Erected 1899. Materials: Catalogue: Watson 1990, No: A.1.34.1, Significance Category:

Damage Types: