Archaeolog	ical Site Report	SiteNo	9/2/100/0002-134
5		Site Name	6 Parkes Street, Victoria West
		Date	
		Project	
		CaseNID	
Page No: 1	<u>SiteAutoID:</u> 27248	Coords	-31.403020, 23.112670

Site Category: Building
Directions:
Medium
SiteComments:
Archive Import History: Visual Description: Three-bay semi-detached (see 89 below) Karoo-type cottage with a straight parapet with heavy edge-moulding and very heavy drip-mouldings over the door and windows. Modern

straight parapet with heavy edge-moulding and very heavy drip-mouldings over the door and windows. Modern door and steel windows. Should be restored as it is part of a group that is of local architectural value. Colours: Site Features: Condition: Good Construction Date: Materials: Plastered brick : Corrugated iron Catalogue: Rudner, 1991, No: 088, Significance Category: A

## AdminComments:

Bibliography archive: Rudner, J and I. Victoria West Survey, 1991, p 42

Damage Types:

