Archaeological Site Report	SiteNo	9/2/100/0002-077
	Site Name	10 Fraser Street, Victoria West
	Date	
	Project	
	CaseNID	
Page No: 1 SiteAutolD: 27289	Coords	-31.403211, 23.115959

Site Category: Building

Directions:

Medium

SiteComments:

Archive Import History: Visual Description: Simple three-bay Karoo-type cottage with heavy cornice and stone stoep. Plaster mouldings at corners. Four-panelled door with three-paned fanlight and old 6x6-paned sash windows. Broad plaster surround at door, narrower surrounds at windows. This attractive cottage is of local architectural value. Colours: Site Features: Condition: Good Construction Date: Materials: Plastered brick: Corrugated iron Catalogue: Rudner, 1991, No: 105, Significance Category: A

AdminComments:

Bibliography archive: Rudner, J and I. Victoria West Survey, 1991, p 47

Damage Types:

