Archaeological Site Report	SiteNo	9/2/100/0002-090
,	Site Name	5 Victoria Street, Victoria West
	Date	
	Project	
	CaseNID	
Page No: 1 SiteAutoID: 27277	Coords	-31.404192, 23.110507

Site Category: Building

Directions:

Medium

SiteComments:

Archive Import History: Visual Description: Three-bay saddle-roofed cottage with shouldered and edge-moulded gables, with a loft door. Verandah with concave roof on facebrick pillars and straight walls with wooden gate. Modern door with twelve-paned fanlight. Windows with louvered shutters (closed). Of local architectural interest in spite of the modern door and facebrick which could be replaced. Colours: Site Features: Condition: Good Construction Date: Materials: Plastered brick: Corrugated iron Catalogue: Rudner, 1991, No: 123, Significance Category: A

AdminComments:

Bibliography archive: Rudner, J and I. Victoria West Survey, 1991, p 53

Damage Types:

