

<b>Archaeological Site Report</b>	<b>SiteNo</b>	9/2/100/0002-023
	<b>Site Name</b>	109 Church Street, Victoria West
	<b>Date</b>	
	<b>Project</b>	
	<b>CaseNID</b>	
	<b>Coords</b>	-31.402230, 23.105769

Page No: 1      **SiteAutoID:** 27312

Site Category: Building

**Directions:**

Medium

**SiteComments:**

Archive Import History: Visual Description: Karoo-type three bay house with pedimented parapet with edge-moulding and cornice. Verandah has ogee roof on square pillars and step-dipped walls. 2x2-panelled double door with upper panels arched and three-paned fanlight. Windows have louvered shutters (closed). Side windows of steel. Heavy quoins around door and windows and heavy bracketed drip mouldings over the openings. This house is in good condition and is of local architectural value despite the steel windows. Colours: Site Features: Condition: Good Construction Date: Materials: Plastered brick : Corrugated iron Catalogue: Rudner, 1991, No: 020, Significance Category: A

**AdminComments:**

Bibliography archive: Rudner, J and I. Victoria West Survey, 1991, p 19

Damage Types: