

<b>Archaeological Site Report</b>	<b>SiteNo</b>	9/2/100/0002-150
	<b>Site Name</b>	122 Church Street, Victoria West
	<b>Date</b>	
	<b>Project</b>	
	<b>CaseNID</b>	
	<b>Coords</b>	-31.401744, 23.105395

Page No: 1      **SiteAutoID:** 27237

Site Category: Building

**Directions:**

Medium

**SiteComments:**

Archive Import History: Visual Description: Three-bay Karoo-type cottage with pedimented parapet with edge-moulding. Verandah has ogee roof on precast pillars and dipped front walls. 3x3-panelled double door with large and small rectangular panes in fanlight. Left window has louvered shutters (closed), right window is of steel. Heavy quoins in the corners and round the door. Drip moulding over door and windows. Cottage is in good condition and of local architectural value. Colours: Site Features: Condition: Good Construction Date: Materials: Plastered brick : Corrugated iron Catalogue: Rudner, 1991, No: 037, Significance Category: A

**AdminComments:**

Bibliography archive: Rudner, J and I. Victoria West Survey, 1991, p 25

Damage Types: