

<b>Archaeological Site Report</b>	<b>SiteNo</b>	9/2/100/0002-148
	<b>Site Name</b>	118 Church Street, Victoria West
	<b>Date</b>	
	<b>Project</b>	
	<b>CaseNID</b>	
	<b>Coords</b>	-31.401818, 23.105502

Page No: 1      **SiteAutoID:** 27240

Site Category: Building

**Directions:**

Medium

**SiteComments:**

Archive Import History: Visual Description: Karoo-type semi-detached (to no. 120) cottage with three bays. Stepped parapet with corner plinths. Verandah with ogee roof and trellis-work supports, railing and gates; Ornamental drip fretwork above. 2x2-panel double door with twelve-paned fanlight. Upper door panels are arched. 6x6-paned sash windows with louvered shutters. Walls have imitation ashlar decor; rustic plaster surrounds with plaster brackets over the door and windows and below the windows. This cottage is of local architectural value. Colours: Site Features: Condition: Good Construction Date: Materials: Plastered brick : Corrugated iron Catalogue: Rudner, 1991, No: 035, Significance Category: A

**AdminComments:**

Bibliography archive: Rudner, J and I. Victoria West Survey, 1991, p 24

Damage Types: