Archaeological Site Report	SiteNo	9/2/100/0002-081
	Site Name	10 Daniel Hugo Street, Victoria West
	Date	
	Project	
	CaseNID	
Page No: 1 SiteAutolD: 27283	Coords	-31.403041, 23.114567

Site Category: Building

Directions:

Medium

SiteComments:

Archive Import History: Visual Description: Small three-bay cottage with saddle-roof between shouldered end-gables with mock chimneys and edge-mouldings. Loft door on right gable. Plain door and window surrounds. Edwardian-type half-glazed door with four-paned fanlight. Louvered shutters (closed) broken and windows are gone. Plain narrow stoep. This empty cottage is in a bad state; it was probably originally thatched and should be restored because of its local architectural value. Colours: Site Features: Condition: Good Construction Date: Materials: Plastered brick: Corrugated iron Catalogue: Rudner, 1991, No: 077, Significance Category: A

AdminComments:

Bibliography archive: Rudner, J and I. Victoria West Survey, 1991, p 38

Damage Types:

