Archaeolog	ical Site Report	SiteNo	9/2/100/0002-082
0	•	Site Name	3 Hugo Street, Victoria West
		Date	
		Project	
		CaseNID	
Page No: 1	SiteAutoID: 27284	Coords	-31.402720, 23.114647

Site Category: Building
Directions:
Medium
SiteComments:
Archive Import History: Visual Description: Four-bay Karoo-type house with stepped edge-moulded parapet
and corpice. Verandah with one roof on wooden posts and straight front walls. Drip fretwork under verandah

and cornice. Verandah with ogee roof on wooden posts and straight front walls. Drip fretwork under verandah edge. Half-glazed door with three-paned fanlight and 6x6-paned sash windows with louvered shutters. A good house of local architectural value. Colours: Site Features: Condition: Good Construction Date: Materials: Plastered brick : Corrugated iron Catalogue: Rudner, 1991, No: 113, Significance Category: A

AdminComments:

Bibliography archive: Rudner, J and I. Victoria West Survey, 1991, p 50

Damage Types:

