

Archaeological Site Report	SiteNo	9/2/100/0002-019
	Site Name	19 Maeder Street, Victoria West
	Date	
	Project	
	CaseNID	
	Coords	-31.403056, 23.120556

Page No: 1 **SiteAutoID:** 27317

Site Category: Building

Directions:

Medium

SiteComments:

Archive Import History: Visual Description: 3+1 bay extended cottage with saddle-roof and stoep. Extension on left has large steel window and modern door. The original part has four-panelled door with two-paned fanlight, 2x2-paned sash windows with louvered shutters. Door and windows surrounded by plaster quoins. End-wall at right end of stoep, steps at left end. An interesting house although it has been spoiled by unsympathetic renovation. Of local architectural value. Colours: Site Features: Condition: Good Construction Date: Materials: Plastered brick : Corrugated iron Catalogue: Rudner, 1991, No: 064, Significance Category: A

AdminComments:

Bibliography archive: Rudner, J and I. Victoria West Survey, 1991, p 33

Damage Types: