

**A PHOTOGRAPH OF THE NORTH EAST ELEVATION OF THE MAIN DWELLING**



**A PHOTOGRAPH OF THE FRONT OF THE DWELLING (SOUTH EAST ELEVATION)**



**A PHOTO OF THE SIDE OF THE MAIN DWELLING FACING JESMOND ROAD (SOUTH WEST ELEVATION)**



**A FURTHER PHOTOGRAPH OF THE SOUTH WEST ELEVATION WITH A ONCE VERANDAH HAVING BEEN ENCLOSED AND CONVERTED INTO A STUDY**



**A PHOTOGRAPH OF THE REAR OF THE BUILDING ( NORTH WEST ELEVATION) SHOWING THE EXTENSION OF AN EXISTING BEDROOM THAT FACES THE POOL.**



**A PHOTOGRAPH OF THE BACK OF THE BUILDING( NORTH WEST ELEVATION ) SHOWING THE VERANDAH THAT HAS BEEN ADDED TO THE MAIN DWELLING.**



**THIS IS A FURTHER PHOTOGRAPH OF THE BACK VERANDAH THAT WAS ADDED ILLEGALLY TO THE MAIN DWELLING.**

