

ROBBEN ISLAND BLUE STONE QUARRY: PHOTOGRAPHS HISTORIC

METHODOLOGY

Images have been reproduced in this document to enable easy access.

The provenance of the photographs is not known.

The photographs are reproduced here as a tool to record and monitor the physical fabric of the quarry wall and its associated landscape.

The background in each photo clearly shows the condition of the wall and its surrounds although this may clearly not have been the intention of the photographer.

The make and model of the camera is not known.

Not all images are labelled.

The original images are curated by RIM.

The exception is the 1993 photograph from the NMC report compiled by Patricia Riley.

Copyright remains with RIM and the photographer in terms of section 27[23] of the National Heritage Resources Act, 25 of 1999.

REFERENCES

Heritage Office of the NSW Department of Planning: *Photographic Recording of Heritage Items using Film or Digital Capture*. 2006.

Ca. 1970's before closure in 1977




Ca Late 1970s early 1980's after closure in 1977



Ca Late 1970s early 1980's after closure in 1977



Ca late 1990's



Ca. 1993

