

ROBBEN ISLAND BLUE STONE QUARRY PHOTOGRAPHS AUGUST AND OCTOBER 2013

A survey was undertaken as part of an HIA commissioned for the construction of a concrete retaining wall on the inside of the sea dyke.

The wall was built between 1963 and 1977 by political prisoners sentenced by the apartheid regime.

The wall was maintained between ca 1980 and ca 1990 by common law prisoners after quarry activities ceased in 1977.

METHODOLOGY

Images have been reproduced in this document to enable easy access.

The digital images are high resolution 4272x3066.

Images were taken with a Fujifilm Finepix S2960 digital camera.

Only the first photograph in each sequence is provided with a digital number.

The photographs were taken 2013-08-26 and 2013-10-17 respectively.

The photographs are not part of a measured survey as the winter weather and nesting birds prevented this.

The images give a good indication of the state of conservation and the height of the water table at the end of winter.

Images start at the survey point BSQ 2 as per WSP Civils' surveyors diagram number 324281/1000 dd February 2012.

The original images are housed at RIM.

Copyright remains with RIM and the photographer in terms of section 27[23] of the National Heritage Resources Act, 25 of 1999.

REFERENCES

Heritage Office of the NSW
Department of Planning:
*Photographic Recording of Heritage
Items using Film or Digital Capture.*
2006.

26 August 2013

DSCF 6141











17 October 2013
DSCF 7743













