

Images below indicates the amount of BORIS and eggs eating into the timber roof trusses.

