



Location in Cromwell Road, Cavendish Park off the lane.



Enclosed front veranda

Streetscape



Asymmetrical gable







Front door.

Inappropriate window addition





Enclosed veranda



Enclosed side veranda



South elevation. Roof repairs evident.



Original outbuilding



Later garage.



Edwardian fireplace.





Front door

Living room door



Original windows

32 CROMWELL ROAD, GLENWOOD..





Inappropriate windows



Later doors on south elevation.



Low rise context, all buildings having asymmetrical gables and verandas.