


38 ST ANDREWS

①




North West Elevation



North West Elevation

(- NOTE: LOTS of foliage blocks the view of the house.)



Front Door - N.W. Elevation






SOUTH WEST ELEVATION - ex. driveway - Corridor between house & o/b.



Brick detail - Air ventilation



Part S.W. Elevation





Front Entrance Hall Area



Bathroom - wall demolished.



Front door area




Window to en-suite bathroom - N.E. ELEVATION.






Part S.W. Elevation ↗



Steps up to front door



N.W. Elevation



Existing open verandah - S.E.