

PHOTOGRAPHS – POST-RECONSTRUCTION April 2023



Street Elevation – East side from Evans Road



East Elevation from driveway



Entrance Stair from parking



East Elevation from parking



SE Corner & entrance



Single garage – existing, unchanged



Garage door to parking – inside view



South elevation to the West end



South elevation – bay window centre



West elevation



Veranda detail – sliding / folding doors



North elevation – south end



North elevation – centre



**North elevation – west end /
scullery**



Veranda detail from the North



Single Garage from the West, NW house corner



North Elevation – West end bay window



South Elevation – Outbuilding



East Elevation – Outbuilding



**Generator -
Outbuilding West End**



Study looking East



Study looking South




Window detail – survived !




Lobby / stairs to loft from study/ main door



Lobby / stairs to loft /main entrance door



Loft looking East from entrance door



Loft looking West from entrance door



Loft looking East from west end




Loft bathroom- looking East



Loft bathroom looking West



Loft bathroom sklight



Loft bathroom looking North



Living / Dining looking West



Living looking East



Dining/ guest wc / skylight looking West



Kitchen looking North from Dining



Kitchen looking West



Kitchen looking East from scullery entry



Scullery looking North




Scullery looking South




Scullery looking West from kitchen



Guest Ensuite looking South



Guest Ensuite looking North



Guest Ensuite looking West