

Annexure 6.2.Exterior perimeter of the Woodstock cemetery



Fig 1. View along Albert Road showing the old wall and street entrance



Fig 2. View along Albert Road towards the Lower Church Street Bridge and intersection



Fig 3. View of the Lower Church Street Bridge and intersection with Albert Road showing heavy traffic



Fig 4. View of the eastern wall looking along Albert Road photo 2018.



Fig 5. View of the northern wall collapse



Fig 6. View of the northern wall showing temporary security measures. 2022.



Fig 7. Wide view of the northern wall and building to the east of the cemetery showing mechanisms proposed to restore the wall.