

Annexure 6.3 Interior annotated photographs



Fig 1. View of the eastern wall looking towards the northern wall. This show the collapse of the cement bricks built on top of the old stone wall. The cement bricks have been cleared.



Fig 2. View of the interior of the cemetery looking towards lower Church Street and the bridge. Certain paths are created from old stone. There is a list of those buried at the cemetery although sometimes the gravestones are illegible because of age.



Fig 3. photograph of the interior of the cemetery looking towards the north wall (2022) which has now partially collapsed.



Fig 4. View of the interior of the cemetery looking south-east towards Albert Road. The area is partially screened from the traffic noise by a row of oleanders.



Fig 5. The Cemetery entrance off Albert Road with security gate.



Fig 6. The old stone perimeter wall off Albert Road.