

**TOPLINE LANDFILL SITE**  
Site Photos taken in July and September 2015



**Figure 1: View north east towards the excavation into which waste is deposited indicated by red arrow. Note waste strewn outside the excavation (July 2015)**



**Figure 2: View west towards the gravel road on the site. Note the burnt waste in the foreground**



**Figure 3: View towards Topline showing the informal housing immediately north of the site. Note the waste strewn across the site (July 2015)**



**Figure 4: Water treatment works west of the site (July 2015)**



Figure 5: View towards the N10 where the car is driving (July 2015)



Figure 6: View towards the north east showing the waste body in foreground on the right of the image the rugby field in the background indicated by a red circle (July 2015)



**Figure 7: View towards the south showing Topline Primary school (July 2015)**



**Figure 8: View towards the south west indicating undisturbed vegetation in the vicinity of the site. Note windblown litter on vegetation (July 2015)**



**Figure 9: View west towards the water treatment works. Note the burnt waste (July 2015)**



**Figure 10: Photo towards the north east showing windblown waste close to the gravel road (September 2015)**



**Figure 11: View towards the south west showing the interior of the excavation . Note the vegetation growing inside the excavation (September 2015)**



**Figure 12: South western wall of the excavation showing rubble and compacted waste (September 2015)**