Draft Basic Assessment Report March 2013






Figure 1: Site 1 Looking south west down the power line corridor from where the access road crosses the path of the line



Figure 2: Site 2a Looking northeast down the power line corridor from the boundary of the Garob property, back towards site 1



Figure 3: Site 2b Looking south west down the power line corridor towards the main public access road which can be seen in the background. The line changes direction at the road and runs alongside the road from this point onward.



Figure 4: Site 3 Looking from the top of the rise along the final section of the power line route along the main gravel road, towards the substation which can be seen in the distance.

Draft Basic Assessment Report March 2013

Location: Substation photographs on Garob Wind Energy Farm subject to a separate EIA process (DEA ref: 14/12/16/3/3/2/279)



Figure 5: Substation 1: Looking north from the end of the OHPL over the area where the substation will be located.



Figure 6: Substation 2: Looking South from the substation down the route where the OHPL will be located.

Draft Basic Assessment Report March 2013

