

NIEKERKSHOOP LANDFILL SITE

Site Photos taken in August and October 2015



Figure 1: Placement of site notice (in progress) at the Main entrance leading to Niekerkshoop landfill (Oct. 2015)



Figure 2: Close up view of the Municipality notice board for the Niekerkshoop landfill (Aug. 2015)



Figure 3: Access road to the site from the main entrance (Oct. 2015)



Figure 4: Entrance to the landfill site showing the sign boards (Oct. 2015)



Figure 5: Interior view of the Niekerkshoop landfill site, picture taken from the east (Oct. 2015)



Figure 6: Niekerkshoop landfill viewed from west (Oct. 2015)



Figure 7: Niekershooop landfill viewed from south (Oct. 2015)



Figure 8: Interior view of the Niekershooop landfill towards the west (Oct. 2015). Waste is currently dumped in the horizontal manner



Figure 9: The Niekerkshoop landfill viewed towards the e south east. Note the large volumes of historically burnt material on site (Oct. 2015)



Figure 10: Niekerkshoop landfill viewed from the north (Oct. 2015)



Figure 11: The grassy sloped around the Niekerkshoop landfill, photograph taken from the back of the cell landfill (Oct. 2015)



Figure 12: View of Niekerkshoop landfill towards the north east (Oct. 2015)



Figure 13: View south west towards the landfill boundary fence. Photo taken from the back of the landfill



Figure 14: The hilly slopes on the south eastern corner of the landfill site



Figure 15: The north north eastern portion of the landfill, showing the entrance to the landfill site



Figure 16: Equipment storage facility located on the northern portion of the landfill site