

Site Photographs

Photo	Description
 A photograph showing a field of tall, dry grass and weeds. In the foreground, there is a pile of discarded plastic bags and other debris. In the background, there are some structures, including what appears to be a red building, and utility poles with power lines under a cloudy sky.	Photo 1: Disturbances on the south-eastern corner of the site included old building rubble, now overgrown with invasive plant species
 A photograph of a steep, vegetated embankment or hillside. The vegetation is dense and green, with various types of shrubs and trees. A concrete or masonry wall is visible at the top of the embankment, partially obscured by the plants. The background shows more trees and a bright sky.	



Photo 3:
Modified
areas on the
eastern
portion of
the site
(truck yard)





Photo 4: A business on the north-western corner and severely compacted turning circle on the western boundary of the site.





Photo 5:
Compacted
soils
dominated
by weedy
pioneer plant
species





Photo 6:
Grassland on
the site with
Vachellia
karroo
occurring
sporadically





Photo 7:
Alien invasive
tree species
dominate the
south-
western
corner of the
site





Photo 8:
Wooded area
in the south-
eastern
corner of the
site,
dominated
by invasive
alien plant
species



