


PHOTOPLATE



Aerial Image: Langaville Ext 12 and its immediate surroundings

CURRENT STATUS OF THE PROJECT SITE AND ITS IMMEDIATE SURROUNDINGS



Figure 1: Vegetation characteristics of the wetlands on site



Figure 2: Upstream of proposed impact. Drains from tailings facility under Tonk meter drive.



Figure 3: General characteristics of Wetland 2



Figure 4: General characteristics of Wetland 3 as seen from Vlakfontein Road south of the pipeline



Figure 5: General characteristics of Wetland 4 as seen from Thema Road



Figure 6: General characteristics of Wetland 5 as seen from Rademan Street.



Figure 7: Characteristics of Pan 2 from Rhokana Street



Figure 8 Characteristics of the canal from Kgaswane Street