

Appendix B: Photographs

Client Name:
Zinoju Coal (Pty) Ltd

Site Location: Magdalena surrounding area,
Dundee, KwaZulu Natal

Project No.
13-727

Photo No.
1

Date:
26 November
2013

Direction Photo Taken:
South

Description:

Local residents within proposed expansion area.



Photo No.
2

Date:
26 November
2013

Direction Photo Taken:
West

Description:

Current access roads to proposed expansion area



Client Name:
Zinoju Coal (Pty)Ltd

Site Location: Magdalena surrounding area,
Dundee, KwaZulu Natal

Project No.
13-727

Photo No.
3

Date:
26 November
2013

Direction Photo Taken:
East

Description:
Expansion area



Photo No.
4

Date:
26 November
2013

Direction Photo Taken:
South

Description:
Exploration borehole located
within proposed expansion
area



Client Name:
Zinoju Coal (Pty)Ltd

Site Location: Magdalena surrounding area,
Dundee, KwaZulu Natal

Project No.
13-727

Photo No.
5

Date:
26 November
2013

Direction Photo Taken:
North westerly

Description:
Section of proposed mining
area, including watercourse
and riverine vegetation



Photo No.
6

Date:
26 November
2013

Direction Photo Taken:
South easterly

Description:
Current mining area and
proposed mining area



Client Name:
Zinoju Coal (Pty)Ltd

Site Location: Magdalena surrounding area,
Dundee, KwaZulu Natal

Project No.
13-727

Photo No.
7

Date:
26 November
2013

Direction Photo Taken:
West

Description:
Natural vegetation within
proposed mining area



Photo No.
8

Date:
26 November
2013

Direction Photo Taken:
South westerly

Description:
Natural vegetation within
proposed mining area



Client Name:
Zinoju Coal (Pty)Ltd

Site Location: Magdalena surrounding area,
Dundee, KwaZulu Natal

Project No.
13-727

Photo No.
9

Date:
26 November
2013

Direction Photo Taken:
East

Description:
Natural vegetation within
proposed mining area



Photo No.
10

Date:
26 November
2013

Direction Photo Taken:

Description:
Dry riverbed, erosion gullies
evident



Client Name:
Zinoju Coal (Pty)Ltd

Site Location: Magdalena surrounding area,
Dundee, KwaZulu Natal

Project No.
13-727

Photo No.
11

Date:
26 November
2013

Direction Photo Taken:
North westerly

Description:
Dry riverbed



Photo No.
12

Date:
26 November
2013

Direction Photo Taken:
West

Description:
Dry riverbed



Client Name:
Zinoju Coal (Pty)Ltd

Site Location: Magdalena surrounding area,
Dundee, KwaZulu Natal

Project No.
13-727

Photo No.
13

Date:
26 November
2013

Direction Photo Taken:
South

Description:
Strong erosion gullies developed. Existing opencast mining at the Magdalena Colliery in the background.



Photo No.
14

Date:
26 November
2013

Direction Photo Taken:
North westerly

Description:
Semi saturated riverbed



Client Name:
Zinoju Coal (Pty)Ltd

Site Location: Magdalena surrounding area,
Dundee, KwaZulu Natal

Project No.
13-727

Photo No.
15

Date:
26 November
2013

Direction Photo Taken:
South west

Description:
Existing opencast pit



Photo No.
16

Date:
26 November
2013

Direction Photo Taken:
South

Description:
Existing opencast pit



Client Name:
Zinoju Coal (Pty)Ltd

Site Location: Magdalena surrounding area,
Dundee, KwaZulu Natal

Project No.
13-727

Photo No.
17

Date:
26 November
2013

Direction Photo Taken:
East

Description:
Watercourse diversion channel
within existing opencast mining
area



Photo No.
18

Date:
26 November
2013

Direction Photo Taken:
North

Description:
Watercourse diversion channel
north of existing opencast pit.

