

Appendix B: Photographs



Figure 1. Google Earth © 2015 image showing points (referred to below) at which site photographs were taken at the proposed Alexandria Community Health Centre site.

Point 1. Public park / play area adjacent to the site, with planted Yellowwood and Coral Trees.



Facing south-west.



Facing north-east.

Point 2. Southern border of the site.



Facing north.



Facing west.



Facing south.



Facing east.

Point 3. South-eastern section of the site.



Facing north.



Facing east.



Facing south.



Facing west.

Point 4. Towards the centre of the site.



Facing north.



Facing east.



Facing south.



Facing west.

Illegal dumping and evidence of past disturbance (rubble heaps) towards the centre of the site.



Illegal dumping (facing south-west).



Rubble heaps – evidence of past disturbance (facing west).

Sewage pipeline servitude / pathway that runs along the north / north-eastern border of the site.



Manhole along sewage pipeline servitude (facing north) with the R72 in the background.



View of the vegetated stream / drainage line along the north-eastern site boundary (facing south-east).
Informal settlement in the background).

Point 6. Northern border of the site.



Facing north (towards the R72).



Facing south-east.



Exposed clayey soil seen towards centre of site (Facing south).



Facing west.