Appendix B Photographs


EPG GAS

Photographs taken on 2018-02-15 and 2018-02-21

Erf 125, Klerksoord X2

NOTICES







Wording of notice





Location of notice 1: Facing Ametis Street against boundary wall at entrance gate. 25° 38' 01.3" South; 28° 07' 55.8" East





Location of notice 2: Facing Ametis Street against boundary wall next to entrance gate at electrical pole. 25° 38' 02.0" South; 28° 07' 55.7" East

SURROUNDING THE PROPERTY



Electrical infrastructure in front of property



Erf 136, Structural Precast Elements (S.P.E.) across the road (Ametis) east from the site.



Erf 136, S.P.E. across the road (Ametis) east from the site.






Mobile tuck shop in Ametis street (in front of S.P.E. property)

Tsipe Engineering property to south east of site









Looking up Ametis street (south to north) with scrap yard to left (west) and Tsipe Engineering and S.P.E. to right (east); north of R566














Granite facility and accommodation adjacent north of site





Signboard seen along the road

Down Ametis street from site looking south towards R566.





Businesses in Willem Cruywagen Street - west of the site

ON SITE







Entrance with gate; surrounded by wall.

Weighbridge to be upgraded









Steel frame to be demolished














Temporary wooden houses for security personnel sleeping on the property (western end of property) and carport (bottom right) to be demolished







Dumping of waste on property





Dumping of bricks on site and property to west





Building from previous business to be demolished

VIEWS FROM CENTRE OF SITE 25° 38' 02.8" South; 28° 07' 53.7" East



Looking east towards entrance, Ametis Street and S.P.E.



Looking south east (steel frame to be demolished)



Looking south (steel frame and building to be demolished) towards property's southern boundary bordering scrap yard



Looking south west towards wooden houses of security personnel



Looking west towards western boundary of property and carport



Looking north west towards bordering property (roofs of building on neighbouring site seen)



Looking north towards northern boundary but view obstructed by building to be demolished



Looking north east towards office building to remain