

PHOTOGRAPHS OF THE SITE TAKEN ON 18 FEBRUARY 2015



Figure 1: The road adjacent to the existing pear orchard.



Figure 2: The road heading towards the southwestern portion of the site.



Figure 3: The existing pear orchard.



Figure 4: The dilapidated and vacant farm worker's cottages.



Figure 5: The southern section of the site



Figure 6: The cottages along the southern boundary of the site that will be maintained. Arrow indicates the existing farm school.



Figure 7: An existing dwelling on site. Note the surrounding vegetation.



Figure 8: The existing sheds on site.



Figure 9: Alien vegetation on site



Figure 10: The disturbed land on site.



Figure 11: Disturbed land on site.



Figure 12: Further examples of the transformed nature of the site.



Figure 13: The sheds



Figure 14: The existing pallet factory.



Figure 15: The pallet factory



Figure 16: Existing access road off the Helshoogte Road.



Figure 17: The site to the west of the Helshoogte Road.



Figure 18: Existing orchards to the west of Helshoogte Road, on site.



Figure 19: The existing trees on site to the west of the Helshoogte Road.



Figure 20: Houses of Cannery Row.



Figure 21: The Helshoogte Road in the vicinity of the site.



Figure 22: The existing RFF Factory Sheds

PHOTOGRAPHS OF THE WETLANDS TAKEN ON 12 MARCH 2015



Figure 23: Wetland located on the northern boundary of the site.



Figure 24: The wetland along the northern boundary of the site looking in a westerly direction.



Figure 25: The wet area on site (due to leaking pipe).



Figure 26: Wetland 3



Figure 27: Wetlands 1 and 2 located near the southeastern corner of the site.



Figure 28: Wetlands 1 and 2.



LAYOUT ITERATIONS ON SITE

PHOTO DIRECTIONS



