



TP1  
(1.0)  
1.1

Position of Test Pit showing depth to bedrock ( ) and refusal depth in metres below existing ground level.



Shale outcrop



Inferred limits of dolerite soils

Site Sketch showing Locality of Test Pits

Scale : Not to Scale

Satellite Imagery: Google Earth

**The Square of Thornville**

**Mondli Consulting Services**

**GeoZone**  
GeoServices

- Slope Stability
- Mine Stability
- Rock Engineering
- Soil Mechanics
- Materials
- Foundation Design

- Site Investigations
- Groundwater
- Mineral Exploration
- Instrumentation
- NHBRC
- Rockfall Protection

• KZN: 1 Mansfield Road, Howick, 3290

Phone: 082 9260626,

• Skype: gerald.allan.davie • E-Mail: info@geozone.co.za • Web: www.geozone.co.za

DATE  
23 March 2023

DRAWN  
G Davie

CHECK  
G.Davie

REFERENCE No.  
22-035

Dwg. No.  
Figure 1