APPENDIX C: PHOTOGRAPHS: BARKLY EAST WASTE DISPOSAL FACILITY



Picture 2015-08-27

Description

Looking north

Site entrance and guardhouse.
Note the weighbridge.
Site entrance will be relocated to directly behind the weighpad.

Photograph taken near Position 1.



Looking south-east.

Signage at site entrance.

Photograph taken near Position 1.



Looking east.

Site notice at entrance.

Photograph taken near Position 1.



Looking south-east.

Site fence. People have been burying animal carcasses in this area of the landfill after hours.

Photograph taken near Position 3.



Looking south-east.

Active landfill cell.

Photograph taken between Positions 3 and 4.



Looking west.

Defunct incinerator cage (future recycling area) in the distance.

Photograph taken near Position 3.



Looking south-west.

New unlined trench. In the distance beyond the fence is the old landfill area.

Photograph taken between Positions 2 and 3.



Looking north.

Old trench

Photograph taken between Positions 2 and 3.



Looking east.

Note the watercourse in the distance beyond the fence. Old landfill trenches to the left.

Photograph taken between Positions 2 and 3.



Looking south.

Defunct incinerator cage. The incinerator is earmarked for demolition, while the cage will be retained and used as a recyclables cage.



Weighpad equipment on the site.



Weighpad equipment on the site.