

APPENDIX C: PHOTOGRAPHS: NONDWENI WASTE DISPOSAL FACILITY



Google Earth satellite image of the Nondweni Waste Facility and its site elements and **photo viewpoints**

Picture	Description
	<p>Looking east-north-east.</p> <p>Fire in landfill area.</p> <p>Photograph taken near Position 1.</p>
	<p>Looking north-west.</p> <p>Widespread evidence of waste burning on the site.</p> <p>Photograph taken near Position 2.</p>
	<p>Looking north-west.</p> <p>Old landfill area.</p> <p>Photograph taken near Position 3.</p>
	<p>Waste burning. The old landfill area appears to still be in use to some extent.</p> <p>Photograph taken between Positions 3 and 5.</p>



Looking east.
Waste sorters working at active landfill area, near the fire and TLB.
Photograph taken near Position 4.



Looking south.
Windblown litter against fence.
Photograph taken near Position 1.



Looking north.
Nondweni residential area in the distance.
Photograph taken near Position 5.



Looking north-east.
Trench soil stockpiles.
Photograph taken near Position 1.



Nquthu municipal truck.