APPENDIX C: PHOTOGRAPHS: SKHEMELELE WASTE FACILITY



Google Earth satellite image of the Skhemelele Waste Facility and its site elements

Picture

Description

Looking north-east.

Site entrance. There is a guard controlling access. Note the guard office

Photograph taken near Position 1.



Looking north-east.

Signage at site entrance.

Photograph taken near Position 1.



Looking east.

Borrow pit into which waste is being disposed.

Photograph taken near Position 2.



Looking west.

Stockpiled recyclables.

Photograph taken near Position 2.



Looking north-north-west.

Enormous borrow pit into which waste is being disposed.

Photograph taken near Position 3.



Looking north-north-west.

Enormous borrow pit into which waste is being disposed.

For a sense of scale, note the green wheelie bin.

Photograph taken near Position 3.





Looking south-west.

Largest borrow bit on right.

Photograph taken near Position 4.



Looking north-west.

Adjacent to site entrance is a delivery point for trucked water.

Photograph taken near Position 1.