

























# LEGEND

	Existing MV
	New MV
	Up Grade MV
	Existing LV
	New LV
	Up Grade LV
	Remove MV/LV Line
	Existing MV Pole
	New MV Pole
	Existing LV Pole
	New LV Pole
	MV & LV Pole
	Existing Trfr
	New Trfr
	Fence
	Street
	Road
	Stay
	Strut
	Zink House
	Wooden House
	Brick House



# ENGINEERING SURVEY DESIGN DRAWING

Reference	CAD-Line Survey-LOU
Effective Date	15/10/2015
Revision	01

Trf	New	New	Remove	Remove	Upgrade	Upgrade	Page
Zone	MV	LV	MV	LV	MV	LV	No
1	7.067	0.473					4 & 6
<b>Total</b>	0.690	0.884	0.296				

LEGEND	
Existing MV	—
New MV	—
Up Grade MV	- - -
Remove MV Line	- - -
Existing Trfr	●
New Trfr	●
Existing MV Pole	●
New MV Pole	○
Stay	├
Strut	┘

	3	
	2	
	1	
JA Mallam	0	23/09/2022
<b>SURVEYOR</b>	<b>REV</b>	<b>SURVEY DATE</b>

<b>FEEDER:</b> MAMPHOKGO 22kv	<b>CUSTOMER:</b> Eskom
<b>PROJECT NO:</b> Boschoek Pegging	
<b>CONDUCTOR:</b>	
<b>LENGTH OF LINE:</b> As Above	<b>PROPERTY:</b> Rem Of Farm Boschoek 752 KS Rem Of Farm Ongezien 717 KS
<b>SURVEYOR:</b> Dick de Bruyn & Associates	<b>CONTACT DETAILS</b>
<b>DRAUGHTSPERSON:</b> JA Mallam	<b>SCALE:</b> 1:1500 <b>PAGE:</b> 3 of 15

**N**

THIS DRAWING IS THE PROPERTY OF ESKOM  
 Disclaimer: Eskom is not responsible for any errors displayed on this drawing

### Boschoek Pegging

40% Bushclearing

Beware Of Water Pipes



Possible Rock

Rem Of Farm Boschoek 752 KS

Rem Of Farm Ongezien 717 KS

Trim 5 Marula Trees

Cut 24 Marula Trees



PROFILE of \_\_\_\_\_ Road \_\_\_\_\_ CROSSING

ROAD No. D4361

FEEDER: MAMPHOKGD 22kv

PROJECT: Boschoek Pegging

CLIENT: Eskom

SCALE Hor. 1:2500 Ver. 1:250

CONDUCTOR: \_\_\_\_\_

SURVEYED By: Dick de Bruyn & Associates

ATTACHMENT HEIGHTS:

A= 9.8m Horz X-Arm

B= 9.8m Horz X-Arm


C= \_\_\_\_\_

D= \_\_\_\_\_


TEMPLATED By: P du Preez

DATE: 25/9/22


DATUM = \_\_\_\_\_



Item	Description
Road Number	D4361
KM Mark	10.2km S/W Of D4362
Road Owner	RAL
Road Surface	Tar
Terrain Level	Fill
Distance to Structure	From Center
From Left	38.2m
From Right	39.6m
Width of Road Reserve	No Fence
Latitude Road	24°54'08.84 S
Longitude Road	29°25'27.44 E
Latitude	
Longitude	



Boschoek Pegging  
40% Bushclearing  
Beware Of Water Pipes  
Possible Rock  
Rem Of Farm Boschoek 752 KS  
Rem Of Farm Ongezien 717 KS  
Trim 5 Marula Trees  
Cut 24 Marula Trees







Boschoek Pegging  
40% Bushclearing  
Beware Of Water Pipes

Possible Rock  
Rem Of Farm Boschoek 752 KS  
Rem Of Farm Ongezien 717 KS


Trim 5 Marula Trees  
Cut 24 Marula Trees






Boschoek Pegging  
40% Bushclearing  
Beware Of Water Pipes


Possible Rock  
Rem Of Farm Boschoek 752 KS  
Rem Of Farm Ongezien 717 KS  
Trim 5 Marula Trees  
Cut 24 Marula Trees








Boschoek Pegging  
40% Bushclearing  
Beware Of Water Pipes  
Possible Rock  
Rem Of Farm Boschoek 752 KS  
Rem Of Farm Ongezien 717 KS  
Trim 5 Marula Trees  
Cut 24 Marula Trees







Boschoek Pegging  
40% Bushclearing  
Beware Of Water Pipes  
Possible Rock  
Rem Of Farm Boschoek 752 KS  
Rem Of Farm Ongezien 717 KS  
Trim 5 Marula Trees  
Cut 24 Marula Trees






Boschoek Pegging  
40% Bushclearing  
Beware Of Water Pipes  
Possible Rock  
Rem Of Farm Boschoek 752 KS  
Rem Of Farm Ongezien 717 KS  
Trim 5 Marula Trees  
Cut 24 Marula Trees






Boschoek Pegging  
40% Bushclearing  
Beware Of Water Pipes

Possible Rock  
Rem Of Farm Boschoek 752 KS  
Rem Of Farm Ongezien 717 KS  
Trim 5 Marula Trees  
Cut 24 Marula Trees



Boschoek Pegging  
40% Bushclearing  
Beware Of Water Pipes


Possible Rock  
Rem Of Farm Boschoek 752 KS  
Rem Of Farm Ongezien 717 KS  
Trim 5 Marula Trees  
Cut 24 Marula Trees







Boschoek Pegging  
40% Bushclearing  
Beware Of Water Pipes

Possible Rock  
Rem Of Farm Boschoek 752 KS  
Rem Of Farm Ongezien 717 KS  
Trim 5 Marula Trees  
Cut 24 Marula Trees





Boschoek Pegging  
40% Bushclearing  
Beware Of Water Pipes  
Possible Rock  
Rem Of Farm Boschoek 752 KS  
Rem Of Farm Ongezien 717 KS  
Trim 5 Marula Trees  
Cut 24 Marula Trees