


# Appendix C: Site Photographs



## Appendix C: Site Photographs



**Photo A:** Northern aspects of the property from the R357. Note the gravel patches interspersing the low vegetation.

**Photo B:** Gravel patches.

**Photo C:** Low growing vegetation with an existing transmission line in the background.

## Appendix C: Site Photographs



**Photo D:** Southern aspects of the property from the R357. Note the gravel patches interspersing the low vegetation.

**Photo E:** Low growing vegetation with an existing transmission line in the background.

**Photo F:** R357 which dissects the Humansrus 3 study area.

## Appendix C: Site Photographs



**Photo G:** Transmission lines running south east to Kronos substation.

**Photo H:** Kronos substation in the distance . Note transmission lines along the gravel road.

**Photo I:** Fence and transmission lines running along the gravel road to Kronos.

**Photo J:** Fence and transmission lines coming from the north.