
ENVIRONMENTAL INCIDENT REPORT SHEET		
Secondary water supply pipelines DATE AND TIME OF RECORDING: 16/02/2016 10:30 am.		
INCIDENT DESCRIPTION: (attach additional documentation e.g. photos or sketches where necessary) Runing trenching activities of the above mentional project numer skeletal venueins were unearthed. The Police is resident engine environmental compliance officer of archaeologist were notified immediately		
Incident number: 1	ime of incident: 16 feb 2016	
Location of incident	Mosoge Village	
reatures damaged	rprox. 3 skeletal vernous of human origen were weather decring trenchines activities	
3. Cause(s) of incident	No viseble indicators of postable avove Sites were noticed before excavation started	
The Police Resident Engineer & ECO were notified immediately. The archaeologist was also notified. Photos were taken. The skeletal remains were lightly covered with soil of the area warricaded. No turther excavation activities are allowed in the area for now.		
 Materials and methods used for mitigation of the incident during and immediately after its Occurrence 	N/A	
5.Disposal methods followed with Contaminated material (where Relevant)	NIA	

6. Steps taken to prevent a re- Occurrence of the incident	N/A
7. Additional actions required by Environmental officer	Make arrangements for archaeologist to Vivitine Site Assist archaeologist with obtaining the necessary documentation to SAHRA for a rescue permit.
Signature of contractor's Representative:	I hereby certify that the above is a true and accurate account of the incident and the corrective and preventive actions taken Signed Date 21FEB 2016
Signature of environmental	I hereby certify that the above is a true and accurate account of the incident and
officer:	the corrective and preventive actions taken Signed Date 2/02/2016



FURTHER EXCAVATION ACTIVITIES WERE CEASED IN THIS AREA





HUMAN SKELETON FOUND DURING EXCAVATION ACTIVITIES

