

GROBLERSHOOP LANDFILL SITE
Site Photos taken in July and September 2015



Figure 1: View towards the East (Sept. 2015)



Figure 2: View towards the East (July 2015)



Figure 3: View North (July 2015)



Figure 4: View North East (July 2015)



Figure 5: View North West (July 2015)



Figure 6: View South (July 2015)



Figure 7: View towards the South East showing plastic bags against the fence on the south western (July 2015)



Figure 8: View towards the south west (July 2015)



Figure 9: View towards the south showing the extend of the disposal of waste on site (Sept.2015)



Figure 10: View South West showing sponge like material disposed on site close to the dilapidated structure (July 2015)



Figure 11: View towards the north west (Sept 2015)



Figure 12: View west towards the N10 showing the disposal of rubbish on site (July 2015)



Figure 13: View West showing proximity of the site to natural vegetation (Sept. 2015)



Figure 14: View towards the informal settlement close to the landfill site (July 2015)



Figure 15: View towards the south east showing the fence located east of the site (July 2015)



Figure 16: Close up of waste around plants (July 2015)



Figure 17: View towards the south east showing a tractor with waste to be disposed of at the site (Sept. 2015)



Figure 18: View towards the water tank in the north eastern part of the site (Sept. 2015)



Figure 19: View towards the north east showing one of the numerous access roads on the landfill site (Sept. 2015)



Figure 20: View towards the north (Sept. 2015)