

PHOTOGRAPHS OF THE EXISTING HOUSE AND NEW ADDITIONS AT 10 PRINCESS ALICE AVENUE, BULWER, DURBAN



Image above: Aerial view of 10 Princess Alice Avenue, Bulwer, Durban

Image on right: Front Boundary Wall and Part Front Elevation of House 10



Image on left: View looking down Princess Alice Avenue, House 10 on left.

Image on right: View looking up Princess Alice Avenue, House 10 on right.

EXTERIOR ELEVATIONS: (MAIN HOUSE)



Image on left: Exg. Main House, Part South-East and North-East Elevation.

Image in centre: Exg. Main House, Part South-East Elevation.

Image on right: Exg. Main House, Front Entrance and Stairs, North-East Elevation.



Image on left: Exg. Main House, North-East Elevation.

Image in centre: Exg. Main House, Part North-East Elevation.

Image on right: Exg. Main House, Part North-East Elevation and Part North-West Elevation.



Image on left: Exg. Main House, South-West Elevation with Exg. Path 3.

Image on right: Exg. Main House, Part South-West Elevation, with Exg. Path 3.

EXTERIOR ELEVATIONS: (EXG. OUTHOUSE , EXG. ENTERTAINMENT AREA & EXG. OUTSIDE TERRACE)



Image on left: Exg. Main House, North-West Elevation and Exg. Outside Terrace with Exg. Swimming Pool.

Image in centre: Exg. Entertainment Area, Part Exg. Outhouse and Exg. Outside Terrace with Exg. Swimming Pool.

Image on right: Exg. Outhouse, Exg. Outside Terrace with Swimming Pool and Exg. Garage.




Image on left: Exg. Path 1.

Image in centre: Exg. Washing Line Area.

Image on left: Exg. Entertainment Area.



Image on left: Exg. Front Boundary Wall, House View, with Part Exg. Entrance 1 and Exg. Pedestrian Entrance.

Image in centre: Exg. Driveway with Exg. Entrance 1 and Exg. Pedestrian Entrance.

Image on right: Exg. Front Boundary Wall, Road View, with Exg. Entrance 1 and Exg. Pedestrian Entrance.



Image on left: Exg. Front Boundary Wall, with Exg. Pedestrian Entrance.