



The black arrow represents the footprint of the 300mm above-ground gabion wall aimed at mitigating the damage caused by sheet erosion on the man-made mound. The wall will extend, slightly, beyond the small green tree to the left of the arrow. The smaller arrow, pointing downwards, is by the estimated end of the gabion wall to the far left, when facing the mound.

The man-made mound dating back to about 2006 when soil from the excavation area was placed over an existing cliff. It is eroding.

Path going up to the K2 excavation area.