

KITTY ELECTRIFICATION

Figure 1: Picture showing existing electricity in the study area



Figure 2: Picture showing existing pole number in the study area



Figure 3: Picture showing the existing vegetation



Figure 4: Picture showing existing road and fence boundary infrastructure



Figure 5: Picture showing pole position of the powerline



Figure 6: Picture showing one of the protected species



Figure 7: Another picture showing another pole position



Figure 8: Another picture showing another pole position



Figure 9: Picture showing road infrastructure in the study area



Figure 10: Picture showing fence boundary and tree species



Figure 11: Another picture showing the tree vegetation as well as existing housing infrastructure

