



**Photo 1: DRDAR State Veterinary Clinic**



**Photo 2: Diesel storage tanks outside clinic**



**Photo 3: Rust at the base of the chimney**



**Photo 4: Rust on the chimney**



**Photo 5: View of the incinerator's chimney indicating the rust**



**Photo 6: Incinerator**



**Photo 7: Incinerator**