



Photo 1: DRDAR State Veterinary Clinic



Photo 2: Inside the clinic, where autopsies on animal carcasses are performed



Photo 3: View of the incinerator's chimney indicating the rust



Photo 4: Incinerator



Photo 5: Waste inside the incinerator after incineration



Photo 6: The resulting ash after incineration