

APPENDIX B

SITE PHOTOGRAPHS: ROOIWAL LANDFILL SITE

	Photograph	Description
1		<p>Vantage point: Perimeter looking south.</p> <p>Disposal of general waste, including barbed wire.</p> <p>Photo taken 02 March 2016.</p>
2		<p>Vantage point: Perimeter looking north west.</p> <p>Disposal of general waste.</p> <p>Photo taken 02 March 2016.</p>

3



Vantage point:
Perimeter
looking north
east.

Disposal and
burning of
general waste.
No access
control applied.

Photo taken 02
March 2016.

4



Vantage point:
Perimeter
looking north
west.

Illegal burning
and dumping of
waste

Photo taken 02
March 2016.

5



Vantage point:
Perimeter
looking south
west.

Disposal of
general waste
on largely
vacant land.

Photo taken 02
March 2016.

6



Vantage point:
Perimeter
looking north
west.

Disposal of
general waste
as well as
discarded
barbed wire on-
site.

Photo taken 02
March 2016.

7



Vantage point:
Perimeter
looking south
east.

Disposal of
general waste

Photo taken 02
March 2016.