


|                |                     |
|----------------|---------------------|
| Reference      | CAD-Line Survey-LOU |
| Effective Date | 15/10/2015          |
| Revision       | 01                  |

100% BUSH CLEARING NEEDED



| LEGEND |                    |
|--------|--------------------|
|        | Proposed Trf       |
|        | Proposed Pole      |
|        | Existing Pole      |
|        | Existing Line      |
|        | Proposed Line      |
|        | Existing Trf       |
|        | Man Hole           |
|        | Existing Lv Bundle |

|          |     |             |
|----------|-----|-------------|
|          | 3   |             |
|          | 2   |             |
|          | 1   |             |
|          | 0   |             |
| SURVEYOR | REV | SURVEY DATE |

|                          |  |                  |  |
|--------------------------|--|------------------|--|
| FEEDER: LEEUKRAAL        | CUSTOMER: BELA BELA LOCAL MUNICIPALITY<br>BH RAPOTOKWANE |                  | <p>THIS DRAWING IS THE PROPERTY OF Eskom<br/>Disclaimer: Eskom is not responsible for any errors displayed on this drawing</p> |
| PROJECT NO: SWA630872872 | PROPERTY:  |                  |  |
| CONDUCTOR:               |  |                  |  |
| LENGTH OF LINE: 600m     |  |                  |  |
| SURVEYOR: Nkuna L        | CONTACT DETAILS: 015 230 1783                            |                  |  |
| DRAUGHTSPERSON: Nkuna L  | SCALE:   | PAGE: [1] of [1] |  |