

**APPENDIX B**

**SITE PHOTOGRAPHS: RIEMVASMAAK WASTE DISPOSAL FACILITY**

Picture	Description
	<p>Illegal burning and dumping of waste outside landfill boundaries</p> <p>Photo taken 31 August 2015</p>
	<p>Vantage point: Perimeter looking west</p> <p>Disposal and burning of general waste. No access control applied.</p> <p>Photo taken 31 August 2015</p>





Vantage point:  
Perimeter looking east

Disposal of general  
waste

Photo taken 31 August  
2015



Vantage point:  
Perimeter looking south

Disposal of general  
waste

Photo taken 31 August  
2015





Vantage point:  
Perimeter looking north

Disposal of general  
waste

Photo taken 31 August  
2015



Vantage point:  
Perimeter facing  
outwards north

General waste dumped  
on site

Photo taken 31 August  
2015





Vantage point:  
Perimeter facing  
outwards west

Vacant land

Photo taken 31 August  
2015



Vantage point:  
Perimeter facing  
outwards east

Vacant land

Photo taken 31 August  
2015





Vantage point:  
Perimeter facing  
outwards south

Vacant land

Photo taken 31 August  
2015



Waste dumped and  
burnt at the entrance of  
the landfill, as well as  
outside of the landfill  
boundaries

Photo taken 31 August  
2015





Entrance to the landfill –  
facing west.

Photo taken 31 August  
2015